

Desktop Max Shopbot Cutting using Aspire/ VCarve Toolpath

March 16, 2021

1. Shopbot Machine

- a. Put on eye and ear protection
- b. Close the doors
- c. Check to see that the machine has been warmed up
- d. Check to see bit is not loose
- e. Raise **Z AXIS 2.5** inches using the **JZ 2.5** command (this is different height than alpha)
- f. Use the proximity switch to set Calibrate. **(C3 keyboard command)**
- g. Calibrate Z AXIS on the table. **(C2 keyboard command)**
- h. Raise **Z AXIS 2.5** inches using the **JZ 2.5** command
- i. Measure thickness of material that you plan to cut.
- j. Attach material to the table using screws
- k. Set new X and Y Origins for your design
 - i. Raise the Z-axis so the bit won't drag on the table
 - ii. Using keyboard jog to the appropriate X and Y location. **(J2 X,Y)**
 - iii. Using keyboard to zero the appropriate X and Y Location. **(Z2)**
 - iv. You set origin.
- l. Select Cut

2. Start up Aspire and VCarve software

- a. Open your file
- b. Select objects you wish to cut
- c. Select Toolpath
- d. Pin Toolpath

3. Click on material setup

- a. Check Z-0 - it should be off the board not materials
- b. Enter the thickness of the material *
 - i. Model position material should be the same thickness of the material.
- c. Go to home start position
 - i. Confirm x and y axis are both zero
 - ii. The z axis should one inch plus the thickness of the material.
- d. Click OK.

4. Go to TOOL PATH OPERATIONS

- a. Select 2D Profile Toolpath
- b. Under cutting depth, select the cut depth of the material (CLS tools).
- c. Select the proper tool -CLS down bit 1/4
- d. Click add tabs to tool pads.
- e. Hit CALCULATE.
- f. Preview toolpath
- g. Click on CLOSE
- h. Select SAVE TOOL PATH and save the file in a shopbot format

5. Start ShopBot Command Console

6. Conduct air cut

- a. Select FILE-LOAD
- b. Load the appropriate file
- c. Select 1 3-D offset
- d. Press ENTER
- e. Turn on the spindle by pressing the big GREEN Button
- f. You should hear a "SOUND" of the spindle now turning
- g. Press ok
- h. After checking that everything is good; press space bar
- i. Return to origin (**J2 0,0**)

7. Perform cut

- a. Select FILE-LOAD
- b. Load the appropriate file
- c. Select **no offset** rather than 1 3-D offset
- d. Press enter
- e. Turn on the spindle by pressing the GREEN Button
- f. You should hear a "SOUND"
- g. Turn on the vacuum
- h. Press enter again to start cut

8. Cut is done

- a. Turn off vacuum (which is so loud you shouldn't forget)

9. Clean up after yourself